

This person is implanted with a medical hearing device manufactured by Cochlear Limited. This device is made of metal and implanted under the skin behind the ear. It may contain a magnet. External components are worn behind the ear, on the head or on the body, e.g. in a pocket. Without these components, this person cannot hear. These components may activate metal detection devices, e.g. airport security detector.



AU Cochlear Ltd (ABN 96 002 618 073) Australia, Tel: +61 2 9428 6555

US Cochlear Americas USA Recipient Customer Service, Tel: +1 (800) 483 3123

CA Cochlear Canada Inc Canada Tel: +1 (800) 483 3123

www.cochlear.com

D1800901 V2



MR Conditional



The implant model information is available on the implant card inside this sleeve. MRI examinations can be performed safely on this person only under very specific conditions. MRI examinations performed under different conditions may result in severe patient injury or device malfunction.

The patient must remove all external components of their hearing implant system before entering a room where an MRI scanner is located.

Full MRI safety information for this implant is available by:

- visiting www.cochlear.com/mri
- calling your regional Cochlear office

